



GARY R. HERBERT
Governor
SPENCER J. COX
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES


MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Minerals Inspection Report

Report Date: 03/02/2016


Reviewed 

Mine Name: GR200 Plus	Permit Number: S/019/0066	Mine Status: Active
Operator Name: GR 200 LLC	Inspection Date: 03/01/2016	Permit Fees: Delinquent
Inspector(s): M. Bradley	Inspection Time: 11:30am	Bond Amount: \$27,100
Attendee(s): McKay Tenney DOGM; Dennis Cosby	Weather: Clear, mild	Bond Escalation: 07/16/2015
Inspection Purpose: Follow up from enforcement		Prior Inspection: 05/18/2015

Conclusions and Recommendations

Location: ~5 miles south of Green River, Utah. McKay Tenney GPS'ed the perimeter of disturbance and found that disturbed area has been reduced from 19 acres to just under 11 acres. Further reduction can be achieved pending possible sale of stockpiled gravel on site. In conversation with Mr. Cosby, it was agreed that, for practicality, the permit should be amended to 10 acres and additional surety provided to cover the expanded area. If the two buildings on site are sold to property owner Chris Dunham for his use for agricultural purposes, such a sale should be documented in the permit file so the buildings could be left in place after mining as part of an agricultural post-mining land use. In addition, any sale of the stockpiled gravel should be done relatively soon or go back into the pit. No photos, camera battery dead.

Elements of Inspection	Evaluated & Commented	Enforcement
1. <i>Permits, Revisions, Transfer, Bonds</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Review of permit and enforcement action, operator is complying with the criteria laid out in the informal conference		
2. <i>Public Safety (shafts, adits, trash, signs, highwalls)</i>	<input type="checkbox"/>	<input type="checkbox"/>
3. <i>Protection of Drainages/Erosion Control</i>	<input type="checkbox"/>	<input type="checkbox"/>
4. <i>Deleterious Material</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Fuel tank has been removed		
5. <i>Roads (maintenance, surfacing, dust control, safety)</i>	<input type="checkbox"/>	<input type="checkbox"/>
6. <i>Reclamation</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Reclamation has progressed satisfactorily in accordance with the guidance outlined in the informal conference		
7. <i>Backfilling/Grading (trenches, pits, roads, highwalls, shafts)</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Backfilling of the excavation has progressed well. Stockpiled material along edge of the upland adjacent to the Green River has been placed back into the pit.		
8. <i>Soils</i>	<input type="checkbox"/>	<input type="checkbox"/>
9. <i>Revegetation</i>	<input type="checkbox"/>	<input type="checkbox"/>
10. <i>Other</i>	<input type="checkbox"/>	<input type="checkbox"/>

Inspector's Signature: 

CC: Chris Dunham, landowner; Dennis Cosby, operator (cosby34@citilink.net); Eric Lewis (elewis@precisionsiteworks.com)

File: /nrwogmfs1/OGM/GROUPS/MINERALS/WP/M019-Grand/S0190066-GR200Plus/inspections/INSP-03012016.pdf

